

Fifty Years of Transformer Problems

°


Gas Cushion Transformers

Transformers Oil Preservation (2)

The "Standard" Oil Conservator

Function:

less O_2 and H_2O
in Oil




"Gas Cushion" Oil Preservation ⁽³⁾


Used mainly in
the United
States

Aim: almost no
 O_2 in Oil

N_2
Cylinder




Gas Cushion (High Pressure) (4)



With load the N₂ pressure goes up to 7 psi


Gas Cushion pressure Change ⁽⁴⁾

With lower Load,
as the oil falls,
the N_2 pressure
also fall and at
3 psi. the N_2 is
pressure is held
by supplying
fresh N_2 from
the "bottle".




Gas (High Pressure (2)) ⁽⁵⁾

Above 7 psi Nitrogen vented to atmosphere



Transformers Oil Preservation ⁽⁶⁾


We found that an over saturated oil by about 2 psi or more, N₂ can come out of solution, in the form of bubbles.



o

Winding Arrangement ⁽⁷⁾

The transformer used the traditional winding arrangement working radially outwards from the core to the HV. The unusual part was the "solid" H / L insulation.




HV Winding with 'extra insulation'

(8)

The "solid" H / L insulation resulted in a high stress occurring on the inside of the HV, so additional crepe tape (yellow) was applied.

Partial discharge in N_2 occurred at the back of the coil (red arrow). & black staining was found.




Insulation ⁽⁹⁾

The black stain was copper oxide.

Lab work revealed that the partial discharge in the N₂ produced an amine compound, which is a derivative of Ammonia, and can dissolve copper oxide from the HV conductors.

Model for tests



Insulation (10)


The amine with Copper Oxide migrated through the crepe paper, and once diluted with the bulk oil, promptly deposited the Copper Oxide on the outside of the coils.

Not a good idea!

Bubbles in Oil (11)

12 mm dia
spheres with
10 kV applied,
in oil super-
saturated with
 N_2 .


Bubbles created
spontaneously




o

“Solid”: HV to LV Insulation

Grounded Shield to reduce impulse transfer to the LV




EE Major Insulation Design circa 1960





Leakage Flux (13)

A leakage flux plot from the J & P transformer book.


As transformer sizes increased, radial fluxes became more significant.



Leakage Flux (12)




There was no shorted turn.




As the leakage flux "cuts" the shield

Hence the shield has a "gap"

Developed view of the shield made using nickel-silver sheet, soldered as necessary







Dielectric losses were present because of poor impregnation


Model confirmed that if dielectric loss high, very high temperatures possible








°C



Time

Nickel Silver melts at 1600 °C




High to Low Insulation Design (14)

The design the Company used at that time consisted of a "solid" wrap of pressboard:-

For 132 kV $d=1''$

For 275 kV $d = 2\frac{1}{4}''$

For 400 kV $d = ??$




High to Low Insulation Design ⁽¹⁶⁾


The cause of the high power factor was found to be due to inadequate processing at site.

So we carried out RIV tests, using an ERA equipment, on all the Company's 275 kV transformers in the country.

275/132 kV Autotransformer at Iver Station (Buckinghamshire)



HF Filter on HV Bushing




High to Low Insulation Design ⁽¹⁷⁾

Where the ERA system detected Partial Discharge (PD), the transformer was taken out of service, the oil drained, high vacuum applied and the unit refilled with de-gassed oil. Then PD testing repeated.


In each and every case the repeat test the PD was not detectable.

Bonneville Power, WA


Ferro-resonance at 500 kV




[1] 230 kV C/B at The Dalles opened




[2] 500 kV C/B at John Day opened



[3] After 8 minutes GAS relay operates




[4] After another 8 minutes



500 kV Disconnect arced when opened!


Site tests on Transformer




Site tests on Transformer

Mag. Current High


The Dalles




Core de-magnetized with battery



Mag. Current much reduced




Problem solved !



Problem due to ferroresonance between parallel 500 kV line conductors

Plots of Voltage, Flux & Mag. Current



EE Co Transformer replaced
with Oerlikon unit

Ferroresonance would not
occur, because Oerlikon
transformer had higher no-
load loss!

Bonneville Power had to change
their switching procedures

- Refer to IEEE PES paper by Dolan, Gillies & Kimbark included in High Power Symposium on High Power Testing, Portland Ore, July 1971

Ferrybridge High Current LV problem.


High Current Lead Problem (18)

The Company had supplied the 570 MVA
275 / 13.8 kV Generator Transformers for
Ferrybridge Power Station.

The LV current on the LV of these
transformers was 22,000 Amps.


In order to save oil the tanks were what we
referred to as “form fit”

“Form Fit” Transformer Tank (19)




570 MVA Generator Transformer

High Current Lead Problem (20)




570 MVA Generator Transformer

High Current Loop caused a current to circulate round the tank (21)




||| Tank Cover Bolts


The Cover Bolts became so hot the tank / cover gasket burnt, and oil ran down the side of the tank! (22)





Even with the bolts insulated, the tank flange was still too hot. So a copper bar was bolted to the underside. This bar had to go round the stiffener at the mid point. (Arrow). (23)



A plan view the tank showing the copper bar. (24)




The current in the bar was proportional to load, with 1000A at 600 MVA ⁽²⁵⁾




Ferrybridge Inadequately Cooled Tapping Coils

[1] 570 MVA Generator Transformer. Conductors at the top of the bottom tapping section inadequately cooled




Solution:- Insulation cut back round most of the coils




Parallel Tapping Coils

Because of the radial component of the leakage flux the four tap sections did not share the current equally.




➤ A re-design was required !

Ferrybridge Power Station cooling tower problem




Gale force wind

Cooling Towers Collapsed !!




Large Generator Transformer, Circulating current in end turns

Smaller End Turns




CTC cables (developed view)



Junction between CTC cables allowed
for circulating current (red)

High temperatures allowed oil to
“breakdown”, producing H_2 plus C, H_2
“attacked” Cu O to produce H_2O (steam)




The end of the individual conductor strands had been broken by escaping steam, so under magnification it looked like a series of "rivers" and formed.




Tap Changer Failure


in Brazil

Transformer Taps



Tap Changer Barrier Board with one tap selected







- On arrival the epoxy barrier board was in numerous pieces.
- Assembling them as a jigsaw resulted in.....

Tapchanger Barrier Board Failure

- Products of the failure on both sides of the board, indicating mechanical failure before electrical failure




- Front




- Back

Detailed Examination


- From inside the transformer tank, looking into a cooling tube showed a “tide mark”



On questioning, it was admitted that the valve to the conservator had been always closed




➤ Generator
Transformer
Tank after
LV Winding
Failure and
Fire




- Damage to Core laminations from hot plasma gas emanating from below




- LV busbars of end phase, forced apart by short circuit forces




Converter transformer with the valve winding next to the core




Collapse of a converter transformer valve winding






The Valve Winding Collapsed into the supporting insulation


Impedance valve to tap section on partially collapsed phase lower




When stripped down another phase of the transformer showed signs of initial collapse



Generator transformers, 3-phase 3-winding




Highgate Converter transformers, 3-phase 3-winding



Insulation damage inside LV



Harmonic Flux overheated end turns on LV's to over 150°C



End of X_1 winding



Reference:


➤ Thermal problems caused by harmonic frequency leakage fluxes in 3-phase, 3 winding converter transformers

by

➤ Forrest & Allard

➤ IEEE Transactions on Power Delivery Jan 2004

Highgate Transformer on test



➤ Thank you for
your attention