NFPA 70®-2020 Edition
National Electrical Code®
TIA Log No.: 1479
Reference: 800.100(B)(2) Informational Note and Informational Note Figure caption
Comment Closing Date: January 29, 2020
Submitter: George Bish, Ring Protect, Inc./Amazon
www.nfpa.org/70

1. Revise 800.100(B)(2) Informational Note and its associated Figure's caption to read as follows:

800.100(B)(2) …
Informational Note: Informational Note Figure 800.100(B)(2) illustrates the connection of the bonding conductor in buildings or structures not equipped with an intersystem bonding termination or a terminal block providing access to the building grounding means.

Informational Note Figure 800.100(B)(2) Illustration of a Grounding Electrode Conductor and a Bonding Conductor in a Communications Installation.

Substantiation: The figure 800.100(B)(2) shows a Grounding Electrode Conductor along with a Bonding Conductor for a Communications System Installation. During the revision process the Informational note was duplicated with Figure 800.100(B)(1) which does show a Bonding Conductor only Installation. This change explains that Figure 800.100(B)(2) is showing a Grounding Electrode Conductor along with a Bonding Conductor in a Communications Installation.

The Informational Note associated with 800.100(B)(2) is reworded to reflect that there is not intersystem bonding terminal.

Emergency Nature: The standard contains an error or an omission that was overlooked during the regular revision process.

Anyone may submit a comment by the closing date indicated above. Please identify the TIA number and forward to the Secretary, Standards Council. SUBMIT A COMMENT